

### TOOLS

In general, your shop area should be organized to have small parts and necessary hand tools (hammers, mallets, screwdrivers, etc.) stored in or near the area where they are normally used. Here again we can not tell you exactly what you may need, but we are listing a few items that will be required. They are as follows:

- Electric welders -- arc welding, MIG welding
- Air compressor for spray painting and power tools
- Band saw
- Drill press
- Drill bit set (sizes to fit your needs)
- Welding clamps
- "C" clamps
- Bench grinder
- 12 foot tape (make sure all tapes are accurate)
- Combination square
- Center punch
- Hammer
- Mallet
- Welders chipping hammer
- Heavy-duty bench vise
- Furniture clamps (with jaw face and t-handle)
- Wire brush
- Electric hand drill OR air hand drill
- Air chisel, jig saw or kett saw (for cutting door lite openings)
- Files
- Sanders
  - Air or electric disc sander
  - Orbital sander
- Aerosol touch-up paint
- Auto body filler (polyester resin type)
- Spatulas for spreading body filler
- Pencil grinder (air or electric)
- Safety equipment
  - Welders helmet
  - Face shields
  - Safety glasses and goggles
  - Leather gloves
  - Respirators (for spray painting)
- Shop should also be equipped with an exhaust fan

